Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	51	engine near2 block near2 heat\$3 same charg\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:30
L2	5	1 and power near2 cord	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:15
L3	0	2 and disconnect	US-PGPUB; USPAT; USOCR; EPO; JPO;	OR	OFF	2005/03/09 15:15
7			DERWENT; IBM_TDB			
L4	5	2 and connect\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:16
L5	55	engine near2 block near2 heat\$3 same sensor	US-PGPUB; USPAT;	OR	OFF	2005/03/09 15:28
			USOCR; EPO; JPO; DERWENT; IBM_TDB			
L6	1	5 and sensor near3 cord	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:23
L7	3	5 and power near2 cord	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09-15:26
L8	0	engine near2 block near2 heat\$3 same current near sensor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:28

L9	0	engine near2 block near2 current near sensor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:29
L10	3	engine near2 block with current near sensor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:29
L11	0	engine near2 heat\$3 same current near2 seansor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:30
L12	45	engine near2 heat\$3 same current near2 sensor.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:30
L13	0	12 and power adj2 cord	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:31
L14	0	12 and cord	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/09 15:31